

FIG. 1A




FIG. 1B




FIG. 2A




FIG. 2B




FIG. 3




FIG. 4A




FIG. 4B




FIG. 5A




FIG. 5B




FIG. 5C




FIG. 6

700

		702A	702B	702C	702D	702E	702F	702G	
#	1	2	3	4	5	6	7		Suspected Location(s)
704a-1	0	0	0	0	0	0	0		Component 1
704b-2	1	0	0	0	0	0	0		Component 1
704c-3	1	1	0	0	0	0	0		Component 1, Component 2
704d-4	1	1	1	0	0	0	0		Component 3
704e-5	1	1	1	1	0	0	0		Component 3, Component 4
704f-6	1	1	1	1	1	0	0		Component 5
704g-7	1	1	1	1	1	1	0		Component 6
704h-8	1	1	1	1	1	1	1		No error

706

708

FIG. 7




FIG. 8B




FIG. 8C




FIG. 9